


## PBI1643CE

Electric distribution box, 16A 3p IN/OUT, output sockets 5x16A 3p Shuko



## PBI1643PC

Electric distribution box, powerCON IN/OUT, output sockets 5x16A 3p Shuko



## PBP1663PC

Electric distribution box, powerCON input, output powerCON x5



## PBP1663CE

Electric distribution box, 16A 3p in, output powerCON x5



## PBP1683PCT

Electric distribution box, powerCON TRUE input, output powerCON TRUE x5



## PBP1683CE

Electric distribution box, 16A 3p in, output powerCON TRUE x5



## PBB1687

Electric distribution box, 16A 3p input plug, output sockets 8x16A 3p Shuko



## PBB1610

Electric distribution box, 16A 19p input plug, output sockets 6x16A 3p



## PBB1632

Electric distribution box, 16A 10p input plug, output sockets 4x16A 3p



## PBB1621

Electric distribution box, 16A 16p input plug, output sockets 6x16A 3p




## PBB1643

Electric distribution box, 16A 3p input plug, output sockets 6x16A 3p Shuko



## PBB3210

Electric distribution box, 32A 3p input plug, output sockets 4x16A 3p



## PBQ1654

Electric distribution box, 16A 3p input plug, output sockets 3x16A 3p



## PBQ1665

Electr. distrib. box, 16A 3p input plug, output sockets 1x16A 3p, 2xpowerCON OUT



## PBQ1676

Electric distribution box, 16A 5p input plug, output sockets 3x16A 3p



## PBQ3265

Electric distribution box, 32A 5p input plug, output sockets 3x32A 5p